

集合風景（イオン駐車場にて）



P5180007

犀川ダム（パッキング）



P5180003

ダムからボート移動（OB資材）



P5180007



P5180009

資材運搬（OB分割搬入）



P5180011

ベルクハイム（補修前）



P5180014

ホース修繕



P5180017

屋根補修開始



P5180020



P5180022



P5180024



P5180026

夕飯準備



P5180027

夕食と会話



P5190028



P5190030

修繕後のベルクハイム



P5190032

水廻り側溝整備



P5190034

修繕後（床）の屋内



P5190036



P5190038

床補修（一部張替）



P5190040

屋食休憩



P5190041



P5190042

昼食休憩



P5190043



P5190046



P5190047

有志たちの集合写真



P5190048

撤収準備



P5190049

帰路（へつり通過）



P5190053



P5190054

帰路(難所通過)



P5190056

ボートでの帰路（3往復運搬）



P5190057



P5190059



P5190062

犀川ダム



P5190063



P5190066



P5190069

ボート最終班の到着とお迎え



P5190072

最終班の到着



P5190073